ECS Configuration Change Request

CCR No. 97-0626A	**Logged Date** 4/18/97	**Rev.** A	**Request Type** CCR

Priority Routine ☐ Urgent ☒ Emergency ☐	**Affected Release**	**Change Class** 11

Title (description) Add Verification_Method to MSS L4s that lacked this attribute.

Documents Affected	**Source Nos** (RID, NCR, Action Item, GSFC CCR, etc.) **or Tech Reference** ECS CCB - AC-96-0561

RTM Change ☒ **Start New Baseline** ☐

Problem

A release B MSS L4 (C-MSS-06890) puts requirements on the Alaska SAR Facility (ASF). ASF, if it happens, has been moved to post B.1 and rtm maintain L4 requirements for ECS.

The MSS Level_4 requiremets must have the "Verification_Method" attribute filled in.

Rev A - Verification_Status column added to Table 3. The following L4s were deleted so they were removed from this CCR (this removed Tables 1 & 2) : C-MSS-03710, C-MSS-60180, C-MSS-66160, and C-MSS-06890.

Proposed Solution

Delete MSS L4 C-MSS-06890.

Insert the "Verification_Method" attributes identified in this CCR.

Requirements and/or links are modified as warranted. For non-allowable attribute values use: `unverified' for acceptance and system verification status; `approved' for L4 status.

Impact Analysis:

Organizations Affected:

	BOO ☐	Contracts ☐	ECS Chief Eng ☒	FOS ☐	M&O ☒
Procurement ☐	QO ☒	Rel. Dev ☒	Rel. A ☐	Rel. C ☐	SCDO Arch. ☐
Science Off ☐	Security ☐	Subcontrct ☐	Sys. Eng ☒	Sys Verf Acpt ☒	

Cost:	None ☒	Small ☐	Medium ☐	Large ☐
		(Not exceeding $100,000)	($100,000 to $500,000)	(Over $500,000)

Schedule: None ☒ Other

Additional LOC _____ Man-Months _____

Materials

Originator Roger Gabin (signed) Roger Gabin 4/28/97
Signature   Date

Office Sys.Engr. Office Manager (signed) Edward Nicosia 4/28/97
Signature   Date

Disposition Approved ☒ Approved w/Comment ☐ Forward ☐ Disapproved ☐

Comments:

CCB Chairperson (signed) Paul Fingerman 4/29/97
Signature   Date

ECS